

**From:** [Jacquelyn Young](#)  
**To:** [Miller, Garyg](#); [Walters, Donn](#); [Gray, David](#); [Coleman, Sam](#); [Meyer, John](#); [Sanchez, Carlos](#)  
**Cc:** [Allen, Bob \(PCS\)](#); [Owens, Rock \(CAO\)](#); [sjones@galvbay.org](#); [Lisa Gossett](#); [Linda Henry](#); [Rodrigo Cantu](#); [latrice.babin@pcs.hctx.net](#); [Utley, Sarah \(CAO\)](#); [Gretchen Knowles](#)  
**Subject:** SJR Flooding Update  
**Date:** Tuesday, May 31, 2016 8:43:14 PM

---

EPA,

Our residents are extremely concerned about the recent flooding and more rain is on the way. As you know, I sent out emails/photos over the weekend and I am now sending out the most recent photos I have. Please see the photos and information below. As soon as I have a response from the agency, I will let our residents know what steps are being taken to ensure the protection of public health and the environment.

1. Recent flooding washed out the Market Street feeder, just south of the Waste Pits along Interstate 10.
2. A group of the permanent buoys are currently to the south at Southwest Shipyard.
3. Surveillance cameras appear to be displaced.
4. The dolphin bumper structure in the San Jacinto River directly east of the Waste Pits. The structure was filled with clean sand and it had a cement top. The structure was reportedly struck by an object traveling down river, releasing the material inside and collapsing the top.
5. Waste Pits on 5/31/16
- 6a,b. Debris shown on Pits

Thank you,  
Jackie Young



1.



9808056



2.



3.



4.



5.



6a.



6b.